



Arlington Industries, Inc.

1 Stauffer Ind. Park - Scranton, Pa. 18517

800-233-4717 Fax : 570-562-0646

www.aifittings.com - E-MAIL : sales @ aifittings.com

Manufacturers of Quality Electrical Products




Installation Instructions For : LV1 Low-Voltage Mounting Bracket

1. Select location between framing members for low-voltage mounting bracket.
2. Use LV1 mounting bracket as a template for wall cut-out.
3. Trace the inside of the mounting bracket at desired location. A level may be used to ensure the bracket is plumb. (see Illustration A)
4. Use wallboard saw to make the cut-out, cutting to the outside of traced line. (see Illustration B)
5. Insert LV1 into cut-out and tighten the mounting screws.
6. Wire low-voltage device per device manufacturer's instructions.
7. Install cover plate if needed.

WARNING: LV1 IS DESIGNED FOR LOW-VOLTAGE, CLASS 2 USE ONLY.

NOTE: All Wiring Must be According to NEC, State and Local Codes.


If you have any questions or if parts are missing Please call our Customer Service Department at 1-800-233-4717. Do not call or return this product to your local store or distributor.



LEVEL

TRACE ALONG THE
INSIDE OF THE LVI
WITH A PENCIL

ILLUSTRATION A



CUT TO THE OUTSIDE OF TRACED
LINE WITH WALLBOARD SAW

ILLUSTRATION B