



# Arlington Industries, Inc.

1 Stauffer Ind. Park - Scranton, Pa. 18517

800-233-4717 Fax : 570-562-0646

www.aifittings.com - E-MAIL : sales @ aifittings.com


Manufacturers of Quality Electrical Products



## Installation Instructions For :GB5P (Zinc) & GBB5P (Bronze) Grounding Bridge w/ GCA1 Conduit Adapter

---

1. Mount GCA1 Conduit Adapter Plate in desired location using three Screws (screws not provided).
2. Install PVC conduit into Conduit Adapter using PVC Cement (not provided) and install Grounding Electrode Conductor in conduit, #6 - #2 AWG Solid Copper.
3. Install Grounding Electrode Conductor From Service Equipment at Lay-In Lug using #6 - #2 AWG Solid Copper\*, #6 - #2 Stranded Copper or Aluminum\*\*\*
4. Attach GB5 / GBB5 to Surface of GCA1 Conduit Adapter Using two Screws inserted into GB5 / GBB5 Mounting Ears (Screws Not Provided).
5. Install Bonding Conductor from Utilities, #14 - #6 AWG Solid Copper\*\*, #4 AWG Solid Copper\*, #14 - #4 AWG Stranded Copper\*\*\*, or #6 - #4 Stranded Aluminum\*\*\*
6. Install Cover W / #10-24 Screw (Provided).



NOTE: All Wiring Must be According to NEC, State and Local Codes.

---

If you have any questions or if parts are missing Please call our Customer Service Department at 1-800-233-4717. Do not call or return this product to your local store or distributor.

\*50 In-Lb Torque \*\*30 In-Lb Torque \*\*\*20 In-Lb Torque

